

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, April 11, 2019	Project Contact:	Brian Clauto
Spread: MP246-247 St#13029-13063 AR288	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Inspected designated streams and wetlands included: H1, SS-26, SS-27, WRR-4, SRR-18, SRR-16, W-KL41, W-KL1, W-Q11, S-Q20, WIJ-10, WQ-10 ECD were in place near all the streams / wetlands, no impacts were observed at the time of the inspection.
- St#13029-13063 controls between these stations were in place and functioning.

Recommended Corrective Action: N/A

Deadline: Within 24hr notification.

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 4/22/

FIELD INSPECTION PHOTO LOG


Project Name: Mountain Valley Pipeline

Date: Thursday, April 11, 2019

- Fig. 1 Designated stream S-RR16 and WKL-41 ECD's are in place and functioning.



- Fig. 2 Above designated streams SS-26 and SS-27, ECD's are in place and functioning.



- Fig. 3 Above designated stream H1, ECD's are in place and functioning.



- Fig. 4 Controls in place at access road AR288

